PROPERTY CONDITION DECLARATION

Property Address/Erf No:	66 GARDEN	STREET K	EURBOMSTRANT
Owner's Full Name:	HOWHERY DERMOT	GRANGER +	MOUSIN
Owner's ID:	5504115027	084	
This Seller's Condition Declarat the responsibility on the Seller I am the registered owner or re to prospective purchasers that, 2 2 2 3 I undertake to disclose in we declaration must form part In some cases, in this Declar of certain components of th potential purchasers to mak Where I have stated in this I Purchaser agrees to absolve	presentative of the registere to the best of my knowledg (DATE) was as stated (DATE) was as s	ential purchasers. ed owner of the able the condition of in this Declaration and the sall known defect agreement. declared that I and the to completing and of the condition o	nove property and declare this property on n. Is and agree that such on unsure of the condition responsibility of the property the
subsequently found to be de	fective.		
Signed by SELLER	a QLD	AUSTRAL'	(A)
Signed by SELLER at 15 SCHOOL TANK	on this <u>LNP</u> day of <u>N</u>	MP214 20	23
et	on this day of	20	
GP King igned by Property Practitioner			
George	on this 14 day of N	larch 20 2	3

Scope of Seller's Condition Declaration:

- Scope of the Seller's Declaration: This Declaration is made in terms of the Seller's personal knowledge of the condition of the components of the property.
- Meaning of "Defect". A significant safety, functional or structural issue which requires urgent remedial attention to ensure that the structure, or component, remains for its use
- Nothing prevents a consumer, for his or her own account, from undertaking a private property inspection to confirm the state of the property before finalising the transaction.

Seller's Condition Declaration to prospective purchasers: (Tick applicable blocks) Note: Where the Property Owner declares "Don't know" in respect of any component of the Property, then the Owner is absolved from any responsibility regarding the disclosure of the condition of that component and the prospective purchaser is advised to conduct an independent investigation of the relevant issue. N/A No Don't Know Are there approved plans for all structures 1 N/A Yes Don't know 2 Roof coverings - any leaks or serious damage N/A Rain goods (gutters & downpipes) - any serious defects Don't know 3 Yes N/A Don't know 4 Roof drainage in order No N/A Roof structure - any serious defects Yes Don't know Hot Water geysers - installation SANS compliant Don't know N/A Yes N/A Don't know Ceilings - damp present Yes 8 Exterior Walls - structural cracks suspected Don't know N/A Don't know N/A Exterior Walls - damp present Yes 10 Interior walls - structural cracks suspected Don't know N/A No 11 Interior walls - damp present No Don't know N/A Floors & slabs - structural damage suspected No Don't know N/A 13 Foundations - structural damage suspected No Don't know N/A 14 Staircases & steps – any safety issues Don't know Automatic gates & doors - any functional or safety issues Yes No Don't know W Fire safety – for linked garages (fire door & firewall present 16 Yes Don't know N/A and compliant) 17 Plumbing & sanitary ware - any serious defects No Don't know N/A 18 Electrical installation - is it defect free and compliant Don't know N/A Gas installation - is it defect free and compliant Yes No Don't know N/A 20 Electric fence - is it defect free and compliant Yes No Don't know NA 21 Storm water management - any known problems No Don't know N/A Swimming pool - is the pool & equipment functional & No Yes Don't know NA compliant with safety regulations Do you know any other serious defects on the property Yes Don't know

Additional information provided by the Seller regarding defects, or potential defects, to the property as declared on the previous page:

PERSE SEE DINEXURE TITLED A BANKSHIA TO ANDEXDRE A PROPERTY CONDITION DECLARATION

Al 2/3/2023

N/A

Erf 66, Garden Street, Keurboomstrand, Plettenberg Bay_known defects

- 1. The Keurbooms property is to be sold "voetstoets". It has been ruled by the courts in South Africa that a seller cannot rely on the "voetstoots" clause if the seller is aware of a latent defect and deliberately concealed or failed to disclose it with the intention to defraud the purchaser. Due to the difficulty in proving the seller's intent and knowledge of latent defects at the time of contracting, a practice has developed whereby parties to a property transaction complete a disclosure form describing all the defects on the property. The seller will make a declaration confirming that the items listed in the said form constitute a full and proper disclosure. If so contracted, this disclosure form can be relied upon by the parties in the event of a dispute arising as a result of the existence of latent defects on the property.
- 2. As the house is not without defects (e.g. asbestos roofing, interior asbestos wall panelling, previous beetle infestation, rising damp in lower bedroom & garage, septic tank no longer in service, structural integrity of rear steps, shower & toilet, structural integrity of main support pillars below the house, damage to bathroom following the recent gas explosion), we would need to disclose this information.
- 3. The Electrical compliance Certificate was done in May 2021 and is valid until 20 May 2023
- The Gas compliance certificate was completed in May 2021 and has expired.
- The Beetle certificate was completed in May 2021 and has expired.
- 6. There is an issue with one of the main support pillars beneath the house it is crumbling and reinforcing is exposed and rusting around most of it's circumference. Large rounded river stones were used in the concrete, instead of smaller angular quarried material, which meets regulation these days. Rounded surfaces vs angular surfaces = less grip for binding materials. The pillars have been supporting the house for 60 years and nothing lasts forever.
- 7. There is an old and disused network of gas pipes and fittings which needs to be removed. Much of it is enclosed inside the knotty pine ceiling. I connected to this system and got burnt in a gas explosion in October last. There are burn marks in the bathroom, ceiling, floor, and walls.
- 8. There is a lot of asbestos sheeting on the interior walls and roof.
- 9. Beneath the house, there are gaping cracks in the bathroom walls and the back concrete staircase is breaking up.
- 10. The downstairs room is damp from water rising through the floor. This is an old problem, due to no damp course being laid underneath the concrete during construction. The problem has worsened in recent years, since the boundary drain inside the border on the Steyn's property to the west, was filled in by the new owners. The drain used to take water from a perennial spring in Granger's property past the 3 houses to the only drain at the bottom of the main road, which crosses into the boundary between Jock Worthington and his neighbour. Unfortunately much of that water is now being diverted under the house. The damp in the downstairs room has been an attraction to ants. Anton Scohltz has removed a nest and treated the area with insecticide. 10. The issue is complicated by an old disused septic tank outside the kitchen staircase and downstairs bathroom, which is acting as a barrier to the now diverted water drainage line this is diverting and trapping water, acting as an underground sill. That water eventually leaks under the house. I think it will have to be dug up, along with the French drain at the bottom of the garden, and a new

May 14/3/2023

stone lined trench dug behind the house from the edge of the top driveway to behind the old water tank and down to the culvert across the main road.

All 14/3/2023

- 11. Neither of the 2 fire extinguishers have pressure and neither work.
- 12. There are no smoke alarms fitted.