

Buffalo City Metropolitan Municipality
East London | Bhisho | King William's Town
Province of the Eastern Cape
South Africa

Website: www.buffalocity.gov.za



**BUFFALO CITY
METROPOLITAN MUNICIPALITY**

Office of the Acting Municipal Manager
PO Box 134, East London, 5200
10th Floor, Trust Centre, East London, 5201

Tel: 043 705 1045 | Fax: 043 743 1941
Email: thembisas@buffalocity.gov.za

Our ref.: Ifayile yethu:	Enq: Imibuzo: MR. Z.C. NYAMZA 043-7052114	Your ref.: Ifayile yakho:
-----------------------------	---	------------------------------

CERTIFICATE OF OCCUPANCY

1 & 2 DWELLING & OUTBLD

This is to certify that the structure on Erf **1557 (9 Connaught Street)** in **King Williams Town** - Plan Number **122991** has been inspected in terms of the National Building Regulations and Building Standards Act 103 of 1977; and including all internal services are found to be in order.

District Building Inspector

Ntsika Sishuba

Date: 20 November 2023

Please Note: *As far as the Building Control Branch of the Buffalo City Metropolitan Municipality was able to ascertain as a result of inspections carried out from time to time by our staff, the building has been erected in accordance with the provision of the Act 103 of 1977.*

Z.C. NYAMZA
CHIEF BUILDING INSPECTOR

2023/11/20 11:21:14

Buffalo City Metropolitan Municipality
East London | Bhisho | King William's Town
Province of the Eastern Cape
South Africa

Website: www.buffalocity.gov.za



**BUFFALO CITY
METROPOLITAN MUNICIPALITY**

Office of the Acting Municipal Manager
PO Box 134, East London, 5200
10th Floor, Trust Centre, East London, 5201

Tel: 043 705 1045 | Fax: 043 743 1941
Email: thembisas@buffalocity.gov.za

Our ref.: Ifayile yethu:	Enq: Imibuzo:	MR. Z.C. NYAMZA 043-7052114	Your ref.: Ifayile yakho:
-----------------------------	------------------	--	------------------------------

CERTIFICATE OF OCCUPANCY

2ND DWELLING / OUTBLD

This is to certify that the structure on Erf 1549 (9 Alexander Road) in King Williams Town - Plan Number 122990 has been inspected in terms of the National Building Regulations and Building Standards Act 103 of 1977; and including all internal services are found to be in order.

District Building Inspector

Ntsika Sishuba

Date: 20 November 2023

Please Note: *As far as the Building Control Branch of the Buffalo City Metropolitan Municipality was able to ascertain as a result of inspections carried out from time to time by our staff, the building has been erected in accordance with the provision of the Act 103 of 1977.*

Z.C. NYAMZA
CHIEF BUILDING INSPECTOR

2023/11/20 11:39:11